

Home Report on

Chartered Surveyors



Report prepared for . Marwan Masaud



Document Index

	ors copy	Docum	ent Index	opt of copt
2	Document	Status	Prepared By	Prepared On
20	Index of Documents	Final	20	12
	SingleSurvey	Final	Dunfermline - Allied Surveyors Scotland Plc	04/10/2013 16:59:16
	MortgageCertificate	Final	Dunfermline - Allied Surveyors Scotland Plc	04/10/2013 16:59:07
	EPC	Final	Dunfermline - Allied Surveyors Scotland Plc	02/10/2013 15:17:44
Jen	PropertyQuestionnaire	Final John	Scottish Administration Centre	04/10/2013 16:37:19
	Additional Documents	Final	Dunfermline - Allied Surveyors Scotland Plc	04/10/2013 16:58:57

Important Notice:

This report has been prepared for the purposes of and use of . Marwan Masaud. Should your name not be on this report then Onesurvey is unable to guarantee that this is a genuine or complete copy of the Home Report. A personalised copy of this Home Report may be obtained at www.onesurvey.org free of charge.

If you are a potential purchaser of this property you may then present your personalised copy of the report to your advisers or mortgage provider with a view to them requesting a transcription report from the appointed Chartered Surveyor.


Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.


SINGLE SURVEY



single survey

survey report on:







PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. ¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

TERMS AND CONDITIONS - WITH MVR - 10CTOBER 2008

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

the Seller;

• any person(s) noting an interest in purchasing the Property from the Seller;

- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

1.5

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the Surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

TERMS AND CONDITIONS – WITH MVR – 10CTOBER 2008

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

2 Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

TERMS AND CONDITIONS - WITH MVR - 10CTOBER 2008

• the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.

 the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

TERMS AND CONDITIONS - WITH MVR - 10CTOBER 2008

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

SERVICES

2.4

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an

TERMS AND CONDITIONS – WITH MVR – 10CTOBER 2008



vendors copy

Jendoi's copy

vendorscopy

vendor's cop

arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, \geq corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- *There are no particularly troublesome or unusual legal restrictions; \geq
- lors copy *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a vendors copy reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

vendorscopy

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

	0 0	
6	Description	The subjects comprise a two storey detached house.
	Accommodation	Ground Floor: Entrance Hall, Lounge, Dining Room, Kitchen, Utility and WC.
	copt	First Floor: Landing, Master Bedroom with En Suite Shower Room, Three further Bedrooms and Family Bathroom.
		128
8	Gross internal floor area (m2)	Jent Jent Jent
	Neighbourhood and location	The property is located to the south-east side of Dunfermline town centre in a modern private residential estate which was built by Redrow Homes, members of the NHBC. Local amenities and facilities are within a fairly easy travelling distance.
	6007 60	الأكوني الأكوني الأكوني
	37 27	277 279 279 279

	<u> </u>	<u> </u>
	Age	The property is estimated to be approximately eight years old.
	dot dot	dor dor
୍ତି	Weather	The was dry during the course of the inspection.
		7 7 7
	Chimney stacks	Not applicable.
	A	A A A A
	Q′d	
	Roofing including roof	The timber pitched roof is covered with tiles. The roof space can be accessed via an attic hatch on the landing ceiling. The roof space is
	space	fully insulated between the ceiling joists.
	20°	Sloping roofs were visually inspected with the sid of hipperdare
		Sloping roofs were visually inspected with the aid of binoculars where required.
4	9.	Flat roofs were visually inspected from vantage points within the
		property and where safe and reasonable to do so from a 3m ladder externally.
		Roof spaces were visually inspected and were entered where there
		was safe and reasonable access, normally defined as being from a
	0	3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the
	0 G	Surveyor deems it safe and reasonable to do so.
	39° 39°	29 <u>29</u> 29
	<u>xo`xo`</u>	
5	Rainwater fittings	Visually inspected from ground level these were seen to be of p.v.c.
10	20	70 70 70
		The main walls are of cavity brick/block construction, mainly
	Main walls	roughcasted externally with a facing brick and tile hung finish.
	4	Visually inspected with the aid of binoculars where required.
	S C	Foundations and concealed parts were not exposed or inspected.
	<u> </u>	
	29 29	50 50 50
	Windows, external doors	The windows and doors throughout the property are of u.p.v.c.
్ట్		sealed double glazed units. External joinery includes the eaves timbers/soffits.
2	2	9. 9. 9.
		Internal and external doors were opened and closed where keys were available.
		Random windows were opened and closed where possible.
	4	Doors and windows were not forced open.
	8	୧ ଟି ଟି ଟି
	G G	G G G
	37 39	37 37 37
_	90°	8 ⁰ . 8 ⁰ . 8 ⁰ .
4	4	
Jer	bot Jendor	and Dunfermline KY11.8NE Ref. no. 42556 Page 2 of 17

survey report

External decorations	Decorated areas include the aforementioned doors/windows and eaves/soffits. Visually inspected.
Conservatories / porches	Not applicable.
Communal areas	Communal areas include the tarmac driveway giving access to the property.
Garages and permanent outbuildings	The driveway provides off street parking and also gives access to the single integral car garage. There are no permanent outbuildings. Visually inspected.
Outside areas and boundaries	Private areas of garden ground are provided to the front, side and rear. Boundaries are formed mainly by timber fencing. Visually inspected.
Ceilings	Visually inspected from floor level these were seen to be plasterboard lined with some having an Artex finish.
Internal walls	The internal walls are mainly plasterboard lined. Visually inspected from floor level. Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
vendors copy	opy Jendors copy Jendors copy

		G	e c	6
		The flooring at ground floor level is	s of solid concrete const	truction
	Floors including sub	whilst the flooring at first floor level		
	floors	construction.	10	10
	0. 70.		<u>,</u> 0.	0
		Surfaces of exposed floors were vi	isually inspected. No ca	arpets or
5	5	floor coverings were lifted.		
		Sub-floor areas were inspected on	ly to the extent visible f	roma
		readily accessible and unfixed hate		
		shoulders" inspection at the acces		
		Physical access to the sub floor ar		Survevor
		deems it is safe and reasonable to		
	0	clearance of 1m between the under		
	0 0	as determined from the access hat		
	0 0			0
	29 29 29	29 B	2 ⁹	39
	. A			
	0	Internal joinery consists of timber of	loors/skirtings/facings	etc The
	Internal joinery and	kitchen has a stainless steel sink v		
5	kitchen fittings 💒	units and incorporates an electric h		
		Built-in cupboards were looked into	o but no stored items w	ere moved.
		Kitchen units were visually inspect	ed excluding appliance	s.
			0 11	
		A A	\$	
		o		
	Chimney breasts and	There is a gas living flame fire in the	ne lounge. The gas fire	was not
		tested.		
	fireplaces	27	27	27
	0	Visually inspected. No testing of th	e flues or fittings was c	arried out.
	0	ACT.	<u>A</u>	0
.0	.0		ોંડો	ř.
4		Decorated areas include walls/ceil	inge	
	Internal decorations	Decorated areas include wails/cell	ingo.	
		Visually inspected.		
		, , , , , , , , , , , , , , , , , , , ,		
	A	A A	A	A
		<u>o</u> , <u>o</u> ,		.0'
	Cellars	Not applicable.	G	G
	6 6	.6	.6	.6
	3	3	- S	5
	<u> </u>		- 20	20
- <u>S</u>	Electricity	There is a mains electricity supply.		S
	50			
14		Accessible parts of the wiring were		
		removing fittings. No tests whatsoe or appliances. Visual inspection do		
		make sure they work properly and		
		standards. If any services are turn		
	A	in the report and will not turn them		State that
				<u>, 2</u> '
	6 6	C C C	G	G
	.6 .6	.6		.6
	S	S.	5	5
	80 80		.8	80
S		all'	A	
20	20	1 VC	v 70	
-				

0° 0			17
Gas	There is a mains gas supply. Accessible parts of the syster removing fittings. No tests wh	atsoever were carrie	d out to the system
70, 70,	or appliances. Visual inspection make sure they work properly standards. If any services are in the report and will not turn	and efficiently and r turned off, the surve	neet modern
Water, plumbing and bathroom fittings	There is a mains cold water s mainly of copper/plastic. The WC have modern sanitarywa	bathroom, en suite s	
	Visual inspection of the acces	27	r tanks, cylinders
Jeno Jeno	and fittings without removing No tests whatsoever were ca		m or appliances.
Heating and hot water	Central heating is provided by is wall mounted in the utility. throughout the property by mo provides domestic hot water i which is located in the landing	The boiler serves par eans of small bore pi n conjunction with a	nel radiators ping and also
dors ndors	Accessible parts of the system communal systems, which we No tests whatsoever were car	ere not inspected.	
70, 70,	101	10°	10
Drainage	Drainage is understood to be	·	
e e e e e e e e e e e e e e e e e e e	Drainage covers etc were not Neither drains nor drainage s		(a)
con co		CON	CON
Fire, smoke and burglar	There is a burglar alarm and a	also two smoke alarr	ns in the property.
Jen alarms	Visually inspected. No tests whatsoever were ca	rried out to the system	m or appliances.
copy	in copy	copy	copy
vendors vendors	vendors	Jendor	vendor
11 Milne R	oad, Dunfermline, KY11 8NF	Ref no 42556	Page 5 of 17

Any additional limits to inspection

Jendors copy

vendors copy

Se

Jendors copy

vendors copy

Jendors copy

It was not possible to inspect floor surfaces as they were concealed by fitted floor coverings/heavy furniture. Our inspection of the roof space was only a head and shoulders inspection.

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

vendors copy

vendorscopy

lendors copy

vendorscopt

vendors copy

Jendor's copy

vendors copy

Sectional Diagram showing elements of a typical house

13

12

Se

Chimney pots 1) Coping stone 2 Chimney head 3) Flashing 4) **Ridge ventilation** 5) **Ridge board** 6) Slates / tiles Valley guttering 8) 9) **Dormer projection** (10) **Dormer flashing Dormer cheeks** Sarking (12) **Roof felt** 13 Trusses 14) 15) Collar Insulation (16) (17) Parapet gutter (18) **Eaves guttering** (19) Rainwater downpipe (20) Verge boards /skews (21) Soffit boards 22) Partiton wall 23 Lath / plaster 24) Chimney breast Window pointing 25) 26) Window sills Rendering 28) **Brickwork / pointing** (29) Bay window projection (30) Lintels (31) Cavity walls / wall ties Subfloor ventilator (32) Damp proof course 33) **Base course** Foundations 35) Solum (36) (37) **Floor joists Floorboards** (38) ndorscop Water tank (39) (40) Hot water tank

Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items. G

59

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories:

G

59

U

59

G

59

N 1					
Category 3		Category 2	.0	Category 1	
Urgent repairs or rep needed now. Failure them may cause pro parts of the property safety hazard. Estim or replacement are r	to deal with blems to other or cause a ates for repairs	Repairs or replaceme requiring future attent estimates are still adv	tion, but	No immediate ac repair is needed.	
08	09.	08		09	.08
Structural	movement	8015	Not	9	aors
Repair category:	1	off	en	e	
Notes:	No significant de	efects noted.	-	4	

Dampnes	s, rot and infestation	copi	cool
Repair category:	1 29 29	29	29
Notes:	No significant defects noted.	80	.80
10	Jen	Jer	Jon

Chimney	stacks	6	
Repair category:	୍ଟି ୍ଟି	ୖୖ	2
Notes:	Not applicable.	.S	6
bot	dof dof	dor	dor
Roofing in	ncluding roof space	70.	701
Repair category:	1		
Notes:	No significant defects noted.	6	0
dors	ndois cot endois cot	endorscot	endorscov

vendors copy

c c	٥ ^٣	<i>് ്</i>
- 96 96	-9	- 90 - 90 -
Category 3	Category 2	Category 1
 Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	requiring future attention, but	No immediate action or repair is needed.

Rainwater	fittings	COP+	6000	600
Repair category:	10	10	LO ^S	LOY
Notes:	Vegetation gr	owth noted in gutter to	the front elevation of th	e property.
2	•	2	5	5

Banait astagany		<u></u>	<u></u>	
Repair category:	- V	<u>6</u>	G*	
Notes:	Hairline cracking r brickwork.	noted through roughca	st and to mortar join	ns between
	DIICKWOIK.			

Windows,	Windows, external doors and joinery								
Repair category:	1 4 4 4								
Notes:	No significant defects noted.								
Jendor's Jer	Double glazed windows can be problematic and over time the operation of same can be affected with opening mechanisms becoming damaged. It is, therefore, likely that maintenance repairs will be required as part of an ongoing maintenance programme. The valuation assumes that the installation of the windows complied with the necessary regulations at the time of installation. External timbers are also slightly weathered.								

Jandor Jandor 11 Milne Road, Dunfermline, KY11 8NF Ref no 42556 Ś

Ś

30

	0° 0	Ŭ G	C C	G
	Category 3	Category 2	Category 1	36
Jer	Urgent repairs or replaceme are needed now. Failure to with them may cause proble to other parts of the propert cause a safety hazard. Estimates for repairs or replacement are needed no	ent Repairs or replacem deal requiring future atten ems estimates are still ac y or	nent No immediate	e action or repair is

Externa	l decorations	CORT	6 copt	C COPY
Repair category	: 10	0	LO ^N	201
Notes:	No significant defects r	oted.	ano	one
			2	2

Conserva	tories / porches	.4	
Repair category:	.00, 00,	.003	.00
Notes:	Not applicable.	59	59
0 ⁰¹	ndo's moot	ndor	ndor
	al areas	20	70.
Repair category:	1		
Notes:	No significant defects noted.	2ª	2
29	29 29	29	29
Garages a	and permanent outbuildings	Jendo'	Jendo.
Repair category:	1		-
Notes:	No significant defects noted.		
orscopt	copy copy	25 copt	copy
bol 2	ndor ^{is} copy	endors	endorscor

	0 0 0	C [×]	0 0 0
			-0
	Category 3	Category 2	Category 1
105	Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	requiring future attention, but	No immediate action or repair is needed.

Outside a	reas and boundaries	6003	
Repair category:	101 101	NO.	10
Notes:	No significant defects noted.	and	and
2	1	1	5

Ceilings	4	A	A	
Repair category:	1		.00	.00
Notes:		tchen is in need of so ay. Shrinkage cracking		plasterwork is
6	nd ^o	ende	endo	ende
-			4	

100	100	40ndb	s ende	vende
Internal w	alls	19	-19 -	
Repair category:	1	A		A
Notes:	Shrinkage crac	king noted through p	lasterwork.	e e
39	39	39	39	39

Floors including sub-		floors	Jeno	Jeno
Repair cat	egory: 1			
Notes:	No significa	ant defects noted.		
6003	CODI	CORT	COQ	600
AOIS	NOIS	AOIS	NOIS	AOIS
Jent	Jent	vent	Jent	Jent

Ś

30

	G	G	C ^r	C.	G
	- ,6	-,6			.6
	Category 3	<u></u>	Category 2	Category 1	
Ş	Urgent repairs or rep are needed now. Fail with them may cause to other parts of the p cause a safety hazar Estimates for repairs replacement are need	ure to deal problems property or d. or		No immediate action needed.	n or repair is

Internal jo	inery and kitchen fittings	6003	6000
Repair category:	10	NOT STATE	NO.
Notes:	Age related wear and tear noted to i	nternal joinery and kitchen	fittings.
7.	1 · · · · ·	. S	1

Chimney	breasts and fire	blaces	A	4		
Repair category:	1	COR.	08	.00		
Notes:	The gas fire was not tested. Current test certification should be exhibited.					
. 6	. 6					

	Internal de	ecorations	4	•	~
	Repair category:	1	4	4	6
	Notes:	Normal wear an	d tear noted.	<u></u>	2
	29	39	29	29	390
100	Cellars	60	Jendo,	Jendo.	Jendo
	Repair category:				
	Notes:	Not applicable.			
	copt	copt	copt	copt	copt
	dore	100 ²	endore	endors	endorse

٦

	c c	6 [°]	c c
			.6 .6
	Category 3	Category 2	Category 1
105	Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	requiring future attention, but	No immediate action or repair is needed.

Electricit	y coot	5003	5 copt	5003
Repair category:	10	NOT T	o	0
Notes:		of our inspection, no re hould be exhibited.	portable defects were	noted. Current

Gas	6	6	6	
Repair category:	1	CO'	601	0
Notes:	Within the limits of test certification sh	f our inspection, no rep nould be exhibited.	portable defects we	re noted. Curre
	00	one	on.	ono

Water, plu	umbing and bathroom fittings		
Repair category:	1 01 01	6	
Notes:	No significant defects noted.	CO.	co.
.0	.0 .0	.0	.0

	Notes:	NO Significant o	delects noted.	, U	
	aor s	dois	8019	dois	8019
Jen	Heating	and hot water	Jene	Jent	John
	Repair category	: 1			
	Notes:		s of our inspection, no n should be exhibited		
of	bois	ondors	endors	endors	ondors
2	1	T 1 Milne Road, Dur	nfermline, KY11 8NF	Ref no 42556	Page 13 of 17

	G (5	G	G	G
	Category 3	Catego	ry 2	Category 1	
Jer	Urgent repairs or replacem are needed now. Failure to with them may cause prob to other parts of the proper cause a safety hazard. Estimates for repairs or replacement are needed no	o deal requirin lems ty or		ut needed.	action or repair is

F Drainage	0	.08		208
Repair category:	129	101	NOT STATE	1010
Notes:	No significant del	fects noted.	ente	ene



Ref no 42556 11 Milne Road, Dunfermline, KY11 8NF

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

		-
Structural movement	4	Repair Categories
Dampness, rot and infestation	1	
Chimney stacks		Category 3:
Roofing including roof space	1	Urgent Repairs or replacement are needed
Rainwater fittings	1	now. Failure to deal with
Main walls	1	them may cause problems
Windows, external doors and joinery	1	to other parts of the property or cause a safety hazard.
External decorations	1	Estimates for repairs or
Conservatories / porches	0	replacement are needed
Communal areas	1	now.
Garages and permanent outbuildings	1	Category 2:
Outside areas and boundaries	1	Repairs or replacement
Ceilings	1	requiring future attention, but estimates are still
Internal walls	1	advised.
Floors including sub-floors	1 9	59
Internal joinery and kitchen fittings	1 0	Category 1:
Chimney breasts and fireplaces	1	No immediate action or repair is needed.
Internal decorations	4	
Cellars		
Electricity	1	
Gas A	1	A A
Water, plumbing and bathroom fittings	1	0
Heating and hot water	1 6	59
Drainage	1	105
	~	~

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

vendoriscopy

endorscopt

Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

A	A	A	4
or(s) is the living a	accommodation on?	e o P	Ground
hree steps or few	ver to a main entrance	door of the property?	[x]YES []NO
ift to the main en	trance door of the prop	perty?	[]YES [x]NO
or openings great	er than 750mm?	Jen	[]YES [x]NO
oilet on the same	e level as the living roo	m and kitchen?	[x]YES []NO
oilet on the same	e level as a bedroom?		[×]YES []NO
ms on the same I	level with no internal st	teps or stairs? 🔬	[]YES [x]NC
restricted parking	g within 25 metres of a	n entrance door to the	• [x]YES[]NO
vendot	vendor	vendo	vendot
	hree steps or few ift to the main en or openings great oilet on the same oilet on the same ms on the same	ift to the main entrance door of the prop or openings greater than 750mm? oilet on the same level as the living roo oilet on the same level as a bedroom? ms on the same level with no internal st	hree steps or fewer to a main entrance door of the property? ift to the main entrance door of the property? or openings greater than 750mm? oilet on the same level as the living room and kitchen?

dorscopt

dorscopt

doi's copy

vendors

vendors

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

All boundaries, rights of way and maintenance liability with regards to this property should be checked. The property is approximately eight years old and therefore will still be covered under its NHBC guarantee.

Estimated re-instatement cost for insurance purposes

£194,000 (One Hundred & Ninety-Four Thousand Pounds)

Valuation and market comments

£190,000 (One Hundred & Ninety Thousand Pounds)

doiscop

Report author:		Aisha Akram,MRICS	<u></u>
Company name:	0	Dunfermline - Allied Surveyors Scot	and Plc
A 60		× 69	A 60

Address: 18a, Dickson Street, Dunfermline, KY12 7SL

Signed:

1endors cc

iendors copy

Date of report:

2 October, 2013

Jendor's copy

doiscopy



MORTGAGE VALUATION REPORT

Mortgage Valuation Report

	Property:	11 Milne Road Dunfermline	Client: Marwan Masaud Tenure: Outright ownership			
5	0	Fife KY11 8NF	ende	onde	ende	
	Date of Inspection:	01 October 2013	Reference:	NB0908	45	

This report has been prepared in response to your recent instructions to carry out a valuation report on the property referred to above. Please note that for most clients purchasing a property, the more detailed HOME CONDITION REPORT is recommended. This report and our inspection to which it refers have been carried out in accordance with the RICS Valuation Standards. Your attention is drawn to the additional comments elsewhere within the report, which set out the extent and limitations of the service provided. This report should be read in conjunction with the instruction acknowledgement. It is normal practice and a requirement of the RICS Valuation Standards regulations to point out that this report is for the use of the party to whom it is addressed, or their named client, or their nominated lenders, and no responsibility is accepted to any third party for the whole, or any part of its contents. Your attention is drawn to the fact that neither the whole, nor any part of this report, or any reference thereto may be included in any document, circular or statement without prior approval in writing as to the form in which it will appear.

LOCATION

The property is located to the south-east side of Dunfermline town centre in a modern private residential estate which was built by Redrow Homes, members of the NHBC. Local amenities and facilities are within a fairly easy travelling distance.

2.1 Age:

8 years

2.0

1.0

The subjects comprise a two storey detached house with private areas of garden ground provided to the front, side and rear.

3.0 CONSTRUCTION

DESCRIPTION

The main walls are of cavity brick/block construction, mainly roughcasted externally with a facing brick finish. The timber pitched roof is covered with tiles.

4.0 ACCOMMODATION


Ground Floor: Entrance Hall, Lounge, Dining Room, Kitchen, Utility and WC.

First Floor: Landing, Master Bedroom with En Suite Shower Room, Three further Bedrooms and Family Bathroom.

	5.0	SERVICES (No tests have been applied to any of the services)						
	Water:	Mains	Electricity:	Mains	Gas:	Mains	Drainage:	Mains
Ş	Central Heati	ng:	Gas fired	. Ch		. Chi		0

6.0 OUTBUILDINGS

	Garage: 🔬	Single integral	l	4		4	4	
	Others: 🔗	None		<u>, </u>		<u>,</u> ?'	°,	
C.	7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.						
		abric of the property appears h age and type of construction	-	d. Internally, the	property has b	been kept in a	a condition	
	8.0	ESSENTIAL REPAIR WORK (as a condition of any mortgage or, to preserve the condition of the property)						
	None	20 ⁵	, o ^s		205		, o ⁵	
- 5	8.1 Retention	recommended:			A.		-1 ¹	
2	9.0	ROADS & FOOTPATHS						
	Made							
	10.0	BUILDINGS INSURANCE	£194,000	GROSS EXTERN AREA	AL FLOOR	149	Square metres	
		This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.						
2	11.0	GENERAL REMARKS						
	All boundaries, rights of way and maintenance liability with regards to this property should be checked. The property is approximately eight years old and therefore it will still be covered under its NHBC guarantee.							
	11.1	RENTAL VALUE – estimated monthly rent assuming 6 month short term assured tenancy £						
105	12.0	VALUATION On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.						
	12.1	Market Value in present condition:	£	190,000		,e ³	690-	
	12.2	Market Value on completion of essential works:	£	4	2015		Jorge	
Jer		Jon	Jen		Jen	3	en	








ENERGY REPORT

energy report

energy report on:







Energy Performance Certificate (EPC)

11 MILNE ROAD, DUNFERMLINE, KY11 8NF

Dwelling type:Detached houseDate of assessment:O1 October 2013Date of certificate:01 October 2013Total floor area:128 m²

Reference number: Type of assessment: Primary Energy Indicator: Main heating and fuel: 9117-0920-9109-0829-7906 RdSAP, existing dwelling 158 kWh/m²/year Boiler and radiators, mains gas

You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly
Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your h	stimated energy costs for your home for 3 years*						
Over 3 years you could save*		£453	report for more information				
* based upon the cost of energy for heating, hot wa	pased upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions						
Very energy efficient - lower running costs	Current Potential Ener	Energy Efficiency Rating					
(81-91) (69-80) (69-80)	85 taking in costs. T	This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.					
(55-68) D (39-54 E	Your cu	rrent rating is band C (73 me in Scotland is band D					
(21-38) F (1-20) G	of the im	ential rating shows the ef provement measures lis endations report.					
Not energy efficient - higher running costs		39	39				
Very environmentally friendly - lower CO_2 emissions	Current Potential Envi	ronmental Impac	t (CO ₂) Rating				
(92 plus) A (81-91) B (69-80) C	85 environr emission	ph shows the effect of yo nent in terms of carbon o ns. The higher the rating, nvironment.	lioxide (CO ₂)				
(39-54 E		rrent rating is band C (72 me in Scotland is band D					
(21-38) F (1-20) G	of the im	ential rating shows the ef pprovement measures lis endations report.					
Not environmentally friendly - higher CO ₂ emissions		29	29				
Top actions you can take to s	save money and mak	e your home mor	e efficient				

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Low energy lighting	£65	£144	
2 Condensing boiler	£2,200 - £3,000	£204	\bigcirc
3 Solar water heating	£4,000 - £6,000	£102	\bigcirc

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

GREEN DEAL

APPROVED

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE



11 MILNE ROAD, DUNFERMLINE, KY11 8NF 01 October 2013 RRN: 9117-0920-9109-0829-7906

Recommendations Report

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, as built, insulated (assumed)	★★★☆	****
Roof	Pitched, 250 mm loft insulation	★★★☆	★★★ ☆
Floor	Solid, insulated (assumed)	-6	-6
Windows	Fully double glazed	★★★ ☆	★★★★☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	Room heaters, mains gas		
Hot water	From main system	★★★☆	★★★☆
Lighting	Low energy lighting in 13% of fixed outlets	★★☆☆☆	★★☆☆☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.9 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.6 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

doiscot

11 MILNE ROAD, DUNFERMLINE, KY11 8NF

01 October 2013 RRN: 9117-0920-9109-0829-7906

Recommendations Report

Estimated en	ergy c	osts for this home)	2	
C ^O	. ⁰ 0	Current energy costs	Potential energy costs	F	Potential future savings
Heating	20.	£1,851 over 3 years	£1,734 over 3 years		181
Hot water		£399 over 3 years	£240 over 3 years		You could
Lighting		£381 over 3 years	£204 over 3 years		save £453
	Totals	£2,631	£2,178		over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0800 512 012. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving Rating after improveme		improvement	Green
Re	commended measures	indicative cost	per year	Energy	Environment	Deal
1	Low energy lighting for all fixed outlets	£65	£48	C 75	C 74	6
2	Replace boiler with new condensing boiler	£2,200 - £3,000	£68	C 77	C 76	
3	Solar water heating	£4,000 - £6,000	£34	C 78	C 78	
4	Solar photovoltaic panels, 2.5 kWp	4 £9,000 - £14,000	4) £210	B 85	B 85	

Measures which have a green deal tick of are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick of may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0800 512 012.

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

Micro CHP

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0800 512 012 or go to www.greenerscotland.org.



11 MILNE ROAD, DUNFERMLINE, KY11 8NF

01 October 2013 RRN: 9117-0920-9109-0829-7906

Recommendations Report

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Low energy lighting

Replacement of traditional light bulbs with energy saving recommended ones will reduce lighting costs over the lifetime of the bulb, and they last up to 12 times longer than ordinary light bulbs. Also consider selecting low energy light fittings when redecorating; contact the Lighting Association for your nearest stockist of Domestic Energy Efficient Lighting Scheme fittings.

2 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to obtain advice from your local authority building standards department and from a qualified heating engineer.

3 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

4 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

For most homes, the vast majority of energy costs come from heating the home. Where applicable to your home, the table below shows the energy that could be saved by insulating the attic and walls, based upon the typical energy use for this building. Numbers shown in brackets are the reduction in energy use possible from each improvement measure.

Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
9,928	N/A	N/A	N/A
2,721	e ^o t	e ^o t	e ^o t
	9,928	Existing dwelling insulation 9,928 N/A	Existing dwelling insulation wall insulation 9,928 N/A N/A

11 MILNE ROAD, DUNFERMLINE, KY11 8NF 01 October 2013 RRN: 9117-0920-9109-0829-7906

Recommendations Report

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page. doisco

Assessor's name: Assessor membership number: Company name/trading name: Address:

Phone number: Email address: Related party disclosure:

vendors copt

lendors copy

Miss Aisha Akram EES/008214 Allied Surveyors Scotland Plc 18a Dickson Street Dunfermline KY12 7SL 01383 728 833 aisha.akram@alliedsurveyorsscotland.com No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Jendorscop

1endors coo

This Certificate and Recommendations Report will be available to view online by any party with access to the report reference number (RRN) and to organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK Governments. If you are the current owner or occupier of this building and do not wish this data to be used by these organisations to contact you in relation to such initiatives, please opt out by visiting www.scottishepcregister.org.uk and your data will be restricted accordingly. Further information on this and on Energy Performance Certificates in general can be found at www.scotland.gov.uk/epc.

Iendor's copt

idors copy

idor's copt

Jendors copy

11 MILNE ROAD, DUNFERMLINE, KY11 8NF

01 October 2013 RRN: 9117-0920-9109-0829-7906

Recommendations Report


Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0800 512 012.



PROPERTY QUESTIONNAIRE



Property address

II Milne Road Dunfermline, Fife KY11 8 NF

Seller(s) Mr. Marwan K. Masaud

Completion date of preparty question point	
Completion date of property questionnaire	

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership 10 yrs
8	How long have you owned the property? 1035
2.	Council tax paid
	Which Council Tax band is your property in? (Please circle)
	A B C D E F G H [202 t] monthly
3.	Parking
	What are the arrangements for parking at your property?
	(Please tick all that apply)
	• Garage
	Allocated parking space
	• Driveway
	Shared parking
	On street
	Resident permit
	Metered parking
	Other (please specify):
4.	Conservation area
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?

5.	Listed buildings	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes/No
6.	Alterations/additions/extensions	
а.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes/No
	<u>If you have answered yes,</u> please describe below the changes which you have made:	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes/No
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes/No)
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes/No
	(ii) Did this work involve any changes to the window or door openings?	Yes/No
	(iii) Please describe the changes made to the windows doors, or patio doo approximate dates when the work was completed):	ors (with
	Please give any guarantees which you received for this work to your solic agent.	itor or estate

7.	Central heating	
а.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).	Yes/No/ Partial
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	If you have answered yes, please answer the three questions below:	
	i) When was your central heating system or partial central heating system installed?	At the Roof Yes/No Hydro-eletric
	(ii) Do you have a maintenance contract for the central heating system?	Yes/No
	If you have answered yes, please give details of the company with which you have a maintenance contract:	Hydro-elestric
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	B_9. \3
8.	Energy Performance Certificate	yes
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes/No
9.	Issues that may have affected your property	None
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes/NO
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes/No
b.	Are you aware of the existence of asbestos in your property?	Yes/No
	If you have answered yes, please give details:	

	ease tick which services are	connected to you	Ir property and give detail	s of the supp
	Services	Connected	Supplier	
	Gas or liquid petroleum gas	Gas	Britch Hydroelei	trie_
	Water mains or private water supply	Yes	Dumfermhine cou	mail
	Electricity	yes	B. Hydro-elestri	ŤĊ.
	Mains drainage	Yes	Dunformbre course	et.
	Telephone	Yes	Talk Talk	
	Cable TV or satellite	Yes	SKY	
	Broadband	Y25	SKY	
Î	there a septic tank system a you have answered yes, plea		o questions below:	Yes/No
	Do you have appropriate con nk?	nsents for the dis	charge from your septic	Yes/No/ Don't know
(ii)	Do you have a maintenance	contract for your	septic tank?	Yes/No
	<u>you have answered yes,</u> plea u have a maintenance contra		the company with which	

11.	Responsibilities for shared or common areas	100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
a. b.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details: Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details:	(Yes/No/ Don't know H act Cing, paterso Service (Yes/No/ Not applicable		
c.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes/No		
d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries? If you have answered yes, please give details:	Yes/No		
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details:	Yes/No		
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) If you have answered yes, please give details:	Yes/No		
12.	Charges associated with your property			
a.	Is there a factor or property manager for your property? <u>If you have answered yes</u> , please provide the name and address, and give details of any deposit held and approximate charges:	VesiNo Hacking paterson and in sume by Bank of scotland		

Is there a common buildings insurance policy?	Ves/No/ Don't know
If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes/No/ Don't know
Please give details of any other charges you have to pay on a regulation of common areas or repair works, for example to a reside maintenance or stair fund.	ular basis for the ints' association, or
Specialist works	
As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes/No
If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? If you have answered yes, please give details:	Yes/No
If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	Yes/No
If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please</u> write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	
	Please give details of any other charges you have to pay on a regulipkeep of common areas or repair works, for example to a resider maintenance or stair fund. Specialist works As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property. As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? If you have answered yes, please give details: If you have answered yes, to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also

14.	Guarantees	State and	dinis in desi				
a.	Are there any guarantees or warranties for any of the following:						
(i)	Electrical work	No	Yes	Don't know	With title deeds	Lost	
(ii)	Roofing	No	Yes	Don't know	With title deeds	Lost	
(iii)	Central heating	No	Yes	Don't know	With title deeds	Lost	
(iv)	National House Building Council (NHBC)	No	Yes	Don't know	With title deeds	Lost	
(v)	Damp course	No	Yes	Don't know	With title / deeds	Lost	
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	Nọ	Yes	Don't know	With title deeds	Lost	
b.	If you have answered 'yes' or 'with titl installations to which the guarantee(s) The electricity (Gas, He	e deeds',) relate(s) ૦૫ ૬૯ ૯	please give	details of House	the work or Buildig	allis	
c.	Are there any outstanding claims under	er any of	the guarante	ees listed a	above?	Yes/No)	
	<u>If you have answered yes,</u> please give						
15.	Boundaries	R. C. C.					
	So far as you are aware, has any bour last 10 years? If you have answered yes, please give		our propert	y been mo	ved in the	Yes/ No Don't know	

16.	Notices that affect your property	
	In the past three years have you ever received a notice:	· · · · · · ·
а.	advising that the owner of a neighbouring property has made a planning application?	Yes/No)
b.	that affects your property in some other way?	Yes/No
C.	that requires you to do any maintenance, repairs or improvements to your property?	Yes/No
	If you have answered yes to any of a-c above, please give the notices to your estate agent, including any notices which arrive at any time before the date of the purchaser of your property.	

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s): _____Mr. M. Masand ____ 3.10.13 Date: